


ELEVATOR RECALL AND SMOKE PRESSURIZATION LOGIC

ELEVATOR LOBBY SMOKE DETECTORS ARE SPliced
WITH OTHER FLOOR DUCT DETECTORS AT THE
ZU-360S MODULE



BUILDING 2 EL-1-02					REV. B	3/7/94
ELEVATOR SHAFT PRESSURIZATION RECALL AND SMOKE LOGIC DIAG.					REV. B	3/7/94
NO PLS TO REC'D/PREP/RW DATE: NONE					REV. C	3/7/94
A	RS	MD	MD	11/94/93 AS-BUILT		
REV. A	REV. B	REV. C	REV. D	REV. E	4B02E0B0A	
00000						